

## Phyllis J Kardos

According to studies there have been "too many" serious accidents in silicon facilities due to "eruption of humid and warm combustible gas and steam from the furnace after a major water leakage." This being the case what plans does PacWest have to prevent this water leakage from taking place? What safety measures are in place to prevent injury and death to the workers?