

Margaret Underwood

I am concerned about fugitive dust coming off of any vehicle hauling raw materials to and from the smelter location. How does PacWest plan to manage toxic fugitive dust both during travel as well as during smelting on site? How will vehicles parked at the smelter be cleaned of particulate matter falling from the stack and escaping holding areas prior to leaving the premises? It has been mentioned by persons working in similar situations having particulate matter on their cars while parked on site. How will the fugitive dust be mitigated?