

Lou Ellyn Jones

Ecology should update the Port of Olympia's clean up plan, -1-Amendment to the 2008 Agreed Order-1- to reflect a more current understanding about the area.

Dredging should be focused on the hot spots with the highest level of contamination. It is not acceptable to clean up only the areas being dredged for navigation into Budd Bay.

Dioxin contamination continues to show up in Budd Inlet indicating it is likely from the Cascade Pole dredged material. Multiple sampling should be taken using DNAPL protocols established by the Environmental Protection Act .

Thank you