

## City of Montgomery

The first test was done under normal operations and the numbers are significantly lower. The second test was taken while draining Aeration Basin(Oxidation ditch) 1. The numbers are though the roof. We clean out our tanks every year and the test was taken while emptying oxidation Ditch 1. I believe the numbers would have been closer to the first test if maintenance was not being preformed. The guy collecting the test didn't think it would matter that much.