

# Ira Yates

To Whom It May Concern,

I am concerned that the proposed list of Best Management Practices for Aggregate Production Operations is not good enough. Facilities along the Pecos River have a unique consequence on the river that need to be considered. For instance, open pits below the surface level of the Pecos drain the river and the evaporates wasting water. Also, much of the water that is discharged into the river is of poor quality further impairing the quality of the river.

Sincerely,

Ira Yates

512-7=970-2589