Stanton Calvert

I believe that the proposed list of Best Management Practices for Aggregate Production Operations is inadequate. For example, they do not address practices to minimize water consumption, noise, and light pollution, as was directed to by the Texas Legislature. The BMPs for the areas they do address — dust and water storage — also need serious improvement.