

Tamborine Berelli

The oil terminal's requirement to conduct an internal integrity assessment for each 2 million gallon oil storage tank every 20 years is not frequent enough.