

Robert Barnes

I strongly request that Ecology revise the Port of Olympia's clean up plan, -1-Amendment to the 2008 Agreed Order-1- to reflect the following:

Dredging should be focused on the hot spots with the highest level of contamination. It is not an acceptable clean up plan for the Port to only dredge the navigational areas in Budd Inlet.

Since continuing surface dioxin contamination in Budd Inlet indicates it is likely from the Cascade Pole dredged material, multiple sampling should be taken using DNAPL protocols established by the Environmental Protection Act . We should not be leaving such a horrible condition for our children, grandchildren and community. What other species fouls the nest for current and future generations? Take action now to make it right.