

Kristen Steffen

Lake Sawyer in Black Diamond is at historically low levels and has been getting lower every summer. This leads to excess plant growth and die-back, increasing sediment accumulation, among many other serious issues like higher water temperatures, deoxygenation, and fish loss. A minimum lake level should be set for this lake and excessive nearby pumping should be stopped to control these many problems.