

Kevin Pierson

There is insufficient data provided in the MDD to determine whether the proposed response action is adequate. There are no groundwater concentrations provided, nor information pertaining to the screened intervals of the monitoring wells. Since the CVOCs are DNAPLs, vertical profiling should be conducted at the monitoring well locations in order to adequately assess the extent of groundwater contamination. It appears additional assessment is also needed since the source of the contamination has not been identified.