

Gary HENDRIX

I have read the proposed list of Best Management Practices for Aggregate Production Operations. I find it rather skimpy and it completely ignores important issues such as noise, water consumption and dark skies best practices. Surely TCEQ can do better.

The organization called Texans for Responsible Aggregate Mining (TRAM) has compiled a list of best practices that TCEQ might use as a guide. Their report is available at https://www.tramtexas.org/_files/ugd/0e6b3e_f9e52de0af7449e7ac205a9234b43f1d.pdf