



## Ellie Kravets

The overview map in the public factsheet for this site seems to have an error in the location of Seep 1. I've attached a copy of the map for the sample locations (originally from the 2003 Geomatrix Investigation Plan, but cited in the 2019 Field Report) which shows that the Seep 1 site is much farther to the west (in the area of the debris field) than shown on the current factsheet for this site. The site labelled as "Seep 1" on the current factsheet seems to correspond with soil sampling location S-4 from the 2003 work plan.



A Avenue Landfill overview map



MAP OF SAMPLING LOCATIONS  
"A" Avenue Landfill Project  
Anacortes, Washington

Project No.  
009156.000

Figure

1